

Total Land Subsidence in the Ranegras Valley, La Paz County
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 1.0 Years 03/17/2014 To 04/05/2015

© MDA 2014 - 2015

Explanation

03/17/2014 To 04/05/2015

Total Land Subsidence

	Decorrelation/No Data
	Greater 40 cm (15.7 in)
	25 - 40 cm (9.8 - 15.7 in)
	15 - 25 cm (5.9 - 9.8 in)
	10 - 15 cm (3.9 - 5.9 in)
	6 - 10 cm (2.4 - 3.9 in)
	4 - 6 cm (1.6 - 2.4 in)
	2 - 4 cm (0.8 - 1.6 in)
	1 - 2 cm (0.4 - 0.8 in)
	0 - 1 cm (0 - 0.4 in)

Subsidence Feature

Hardrock

CAP Canal

Highways and Interstates


Interstate

US

State

Roads

Railway



1:125,000

0 0.5 1 2 3 4 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 4/8/2015

